



# COUPLE6 ALIGNMENT REPORT




## REPORT ISSUED BY:

9 Mechanics co.,ltd  
1/99 moo12 Bangpheedai Bangphee Samuthprakan  
02-751-0755 , 086-667-8789

## COMPANY / JOB INFORMATION

Machine Name            MOTOR PUMP 132KW. CDP-2  
Company Name            Amita (Thailand)  
Location  
Address  
  
City  
State  
Postal Code(ZIP)  
Country  
Notes

## MACHINE SETUP



UNITS

OFFSET = mm, ANGLE = mm/100mm




## TARGET INFORMATION

MODEL NUMBER :  
Calib. Due : September 2018

Serial Number : 80-00256  
FW REV. : 3.217

# ALIGNMENT RESULTS

## SIDE VIEW / VERT.



**GAP**


**-0.01**

RPM	TOLERANCES	
	ACCE...	EXCEL...
1200+		
OFFSET	0.10	0.06
ANGLE	0.08	0.05
GAP	0.14	0.09

**OFFSET**

**0.02**

## TOP VIEW / HORIZ.



**GAP**

**0.01**


RPM	TOLERANCES	
	ACCE...	EXCEL...
1200+		
OFFSET	0.10	0.06
ANGLE	0.08	0.05
GAP	0.14	0.09

**OFFSET**

**0.01**

# SOFT FOOT

FOOT	TIGHT	LOOSE	CHAN...	NOTES
1	---	---	---	N/A
2	---	---	---	N/A
3	---	---	---	N/A
4	---	---	---	N/A



# REPEATABILITY

#	V Offset	V Gap	H Offset	H Gap	DATE	TIME	SPAN	#POINTS	MODE	METHOD
✓ 1	0.02	-0.01	0.01	0.01	4/16/2022	2:05 PM	357.7°	49	Coupled	Auto Clock



